




OK-5117H

ASSEMBLY INSTRUCTION

1. INDOOR USE ONLY

2. REPLACE THE BULB AFTER THE BULB GETS COOL

Assembly steps:



Step 1. Put the bulb (B) in the socket (A1) and insert glass shade (C).

Step 2. Push the glass beat (D) on to clips (A2) and secure with pins (E).

Step 3. Attach the assembly (F) to nipple (A3) and secure with loop (G).

Step 4. Tighten loop (G1) on the tube (I).

Step 5. Loosen screw (J) and pass canopy (K) over the tube (I).

Step 6. Tighten loop (L) on the tube (I).

Step 7. Pass the main wire through the links of chain, loop (G1), canopy (K), tube (I) and loop (L).

Step 8. Attach first link and last link (H) of chain to the loops (G1) and (G).

Step 9. Connect wire to the power supply cord.

Step 10. Raise the canopy (K) to ceiling and secure it by tightening the screw (J).

Step 11. Hang the Loop (L) on the hook on ceiling.

After completed the above instruction, please check once more to ensure its safety. Then you may turn the power on. If the external cable or cord is damaged, it shall be replaced by the qualified person to avoid hazard.